

Confidential Claim Retracted

Authorized by: SC

Date: 4/25/13

INSPECTION RECORD
SOLID MINERALS

MAY 23 1983



PUEBLO OF LAGUNA

DATE OF INSPECTION May 2, 1983

DMO Albuquerque STATE NM

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
Laguna 1	Anaconda	V7	1	1.0 / 2.0	Uranium	Lease
Laguna 4	Anaconda	V7	1	1.5 / 3.0	Uranium	Lease
Laguna 8	Anaconda	V7	1	0.5 / 1.0	Uranium	Lease
				/		
				/		
				/		
				/		
				/		
				/		

TYPE OF INSPECTION (CHECK ONE) / / MINE / / EXPLORATION / XX / MINE ABANDONMENT
/ / TECH EXAM, EA / / INACTIVE / / OTHER

PURPOSE OF INSPECTION Assure compliance with temporary abandonment requirements; observe current condition of mine site.

BRIEF DESCRIPTION OF INSPECTION See attached sheet

MINE NAME Jackpile-Paguate Mine DESIGNATED OPERATOR Anaconda Minerals

DATE ORIGINAL MINE PLAN SUBMITTED 2-25-77 DATE ORIGINAL MINE PLAN APPROVED NA

DATE MODIFIED MINE PLAN SUBMITTED 3-16-82 DATE MODIFIED MINE PLAN APPROVED NA

IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: NA

DATE ORIGINAL EXPL. PLAN SUBMITTED NA DATE ORIGINAL EXPL. PLAN APPROVED NA

DATE MODIFIED EXPL. PLAN SUBMITTED NA DATE MODIFIED EXPL. PLAN APPROVED NA

BLM INSPECTOR(S) AND TITLES(S) Dale C. Jones, District Mining Supervisor; Marc Nelson, Environmental Scientist

SURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION None

NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION None

NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION None

HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0.5

HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 0.5

TOTAL TRAVEL TIME 2.0 TOTAL OFFICE TIME 1.0

WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / XX / NO
IF YES, PREPARE NONCOMPLIANCE REPORT

WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / XX / YES / / NO
IF YES, PREPARE UNDESIRABLE EVENT REPORT

PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

Dale C. Jones
Dale C. Jones

CONFIDENTIAL



9403974

POL-EPA01-0001674

Several gullies in waste dump slopes have become larger, and a few cracks are developing in the Gavilan Mesa Highwall. However, none of the gullies or cracks appear to indicate an increased possibility of massive slope or highwall failure. The water level in the South Paguate Pit has risen several feet and is now above the P-13 Mine adits. Anaconda personnel were salvaging miscellaneous surface equipment in the Paguate Pit, presumably for the equipment auction that will be held at the mine site in the near future.

Berms to prevent the erosion of protore into the Rio Paguate are in need of repair, especially along protore stockpile 10. Also, at least one gate in the North Paguate Pit was open and would not prevent livestock access to water ponded in the pit bottom. Anaconda will be advised to inspect, repair and maintain all erosion control berms, fences and gates as necessary.

No violations of approved operating plans, lease terms, or temporary abandonment requirements were observed.

cc:

Area Director, Albuquerque Area Office, BIA

Superintendent, Laguna Agency, BIA

~~G~~Governor, Pueblo of Laguna

Nordhaus, Haltom and Taylor

Area Manager, Rio Puerco RA

DMM-Mining

Inspection File: Laguna 1, 4 and 8

IR file

Chron

017:DCJones:tt:5/10/83

XC: Ron J. Solimon

RECEIVED

MAY 23 1983

PUEBLO OF LAGUNA
GOVERNOR'S OFFICE

POL-EPA01-0001675

CONFIDENTIAL